

Don't become part of the circuit

✓ Connect earthing cable close to welding location.

✓ Wear insulated and dry protective gear.

✗ Avoid wet working conditions.